

# ER. BINDESHWAR PANDIT

B.E(Civil),M.E,FIV,MIE

MCD Licensed Engineer E-00099  
MCD Structural Engineer S.E-26  
Govt. Regd. Valuer U/S 34 (AB) of 1957  
Income Tax  
Structural Designer  
Chartered Engineer  
Registered Valuer IBBI

Address:  
264,D.A Flat, Phase-IV  
Nimri Colony,Ashok Vihar  
Delhi-110052  
Off: 5, Sanjay Nagar,Delhi-110007  
Mobile No.-9810988628, 9821368002  
E-mail ID :- [bpandit2013@gmail.com](mailto:bpandit2013@gmail.com)

Ref.No. BPA/SSC/SPSMV/DEL/2023/42

Date:-14.06.2023

## BUILDING SAFETY CERTIFICATE

Address of property : Salwan Public School  
Kondly Gharouli Complex  
Mayur Vihar Phase-III  
Delhi-110096

Name of owner : Salwan Education Trust (Regd)


School Building is bounded as under:-


North - Park      South - Residential Flat  
East - Park      West - Main Road


I had visually inspected the above cited School Building on dated 14.06.2023. The Building consist of two blocks i.e. old block and new block. Both the block contains Ground Floor, First Floor, Second Floor and Third Floor with terrace. During the inspection I observed that the building is RCC framed structure having RCC Columns, Beams and slab with 230 mm Brick wall. The structure contains Square Column, Rectangular Column as well as Circular Columns The size of square column is 400X400mm, rectangular column is 400X600 mm and circular column is 400mm dia. The old block structure has completed in 1999 and new construction in 2003. I have not found any cracks, deflection, buckling, crippling and bending in the RCC structure. The physical condition of structure is good due to periodic maintenance.

The above mentioned existing building satisfies the safety requirement and the structural design including safety from natural hazards based on soil conditions has been duly incorporated in the design and construction.

In my view the above said building structure is safe and sound.

  
Principal  
Salwan Public School  
Mayur Vihar Phase-III,  
Delhi-110096

  
Director  
Salwan Public School  
Kondli Gharouli Complex  
Mayur Vihar Phase-III,  
Delhi-110096

  
(Er. Bindeshwar Pandit)  
Structure Engineer  
BINDESHWAR PANDIT  
MCD Structural Engineer  
License No.SE-26  
264, D.A. Flats, Nimri Colony